BRIDGE FIELDS RESOURCES SDN BHD [693996-W]

Office: No. 9-1, Jalan USJ10/1G, 47620 Subang Jaya, Selangor Darul Ehsan, Malaysia.
Factory: Lot 4, Jalan Zurah 5B, Pusat Perindustrian Zurah, 44200 Rasa, Hulu Selangor
Tel : +(603) 5633 8444 Fax : +(603) 5634 5333 Website : www.bridgefields.com
Email : sales@bridgefields.com / asmipudin@bridgefields.com

MATERIAL SAFETY DATA SHEET

1.0 COMPANY IDENTIFICATION

1.1	Commercial Name	:	Bridge Fields Resources Sdn Bhd
1.2	Address	:	9-1 USJ 10/1G, Taipan Crest, 47620 Subang Jaya, Selangor
1.3	Telephone	:	+603-5633 8444
1.4	Email	:	asmipudin@bridgefields.com

2.0 PRODUCT IDENTIFICATION

2.1	Product's Model	:	**ECOTYL-55**
2.2	Product's Type	:	Butyl Reclaimed Rubber
2.3	Product's Trade Name	:	Butyl Rubber
2.4	Product's Brand	:	Grenviro
2.5	Product's Composition (per KG)	:	

Material	%	CAS No
Rejected Rubber Products	70 - 80	9006-04-6
Calcium Carbonate	10 – 20	1317-65-3
Paraffinic Oil	3 - 5	8012-95-1
Carbon Black	15 - 20	1333-86-4
Stearic Acid	2 - 4	57-11-4

3.0 HAZARD IDENTIFICATION

3.1	Health Hazards		
	1. Inhalation	:	Not applicable at ambient temperature
	2. Skin Contact	:	Unlikely to be a skin irritant
	3. Eye Contact	:	Unlikely to cause eye contact
	4. Ingestion	:	Unlikely to be harmful unless excessively taken
3.2	Physical / Chemical Hazards	:	None identified
3.3	Environmental Hazards	:	None identified

4.0 FIRST AID MEASURES

4.1	Inhalation	:	Immediately get into fresh air
4.2	Skin Contact	:	Wash with plenty of soap & water
4.3	Eye Contact	:	Wash with plenty of soap & water and seek medical treatment

5.0 FIRE FIGHTING MEASURES

5.1	Extinguisher Data	:	Water spray, foam, carbon dioxide, dry chemical
5.2	Specific Hazards	:	None
5.3	Special Protective	:	Protective clothing and self-contained breathing equipment should be made available

6.0 ACCIDENTAL RELEASE MEASURES

6.1	Personal Precautions	:	No special precautions required
6.2	Environmental Precautions	:	No special precautions required
6.3	Method for Cleaning Up	:	Sweep up and transfer product to suitably labelled containers for disposal at an approved site.

7.0 HANDLING AND STORAGE

7.1	Handling	:	As per the widely accepted industrial Housekeeping Practices
7.2	Storage	:	Store in cool, dry place away from Sunlight

BRIDGE FIELDS RESOURCES SDN BHD [693996-W]

Office: No. 9-1, Jalan USJ10/1G, 47620 Subang Jaya, Selangor Darul Ehsan, Malaysia.
Factory: Lot 4, Jalan Zurah 5B, Pusat Perindustrian Zurah, 44200 Rasa, Hulu Selangor
Tel : +(603) 5633 8444 Fax : +(603) 5634 5333 Website : www.bridgefields.com
Email : sales@bridgefields.com / asmipudin@bridgefields.com

8.0	**EXPOSURE CONTROLS/PERSONAL PROTECTION**		
8.1	General Precautions	:	As per the widely accepted industrial Hygiene Practices
8.2	Ventilation	:	Adequate ventilation is required
8.3	Occupational Exposure Limits	:	Not Established
8.4	Personal Protective Equipment	:	Protective apparatus and self-contained breathing equipment should be made available
9.0	**PHYSICAL DATA**		
9.1	Form/Color/Odor	:	Bale, Sheet/ Black / Faint
9.2	PH	:	Not applicable
9.3	Boiling Point (ºc)	:	Not applicable
9.4	Solidification Point (ºc)	:	Not applicable
9.5	Flash Point	:	Not applicable
9.6	Auto-Ignition Temperature (ºc)	:	> 200 ºC
9.7	Explosive/Oxidizing Properties	:	Not applicable
9.8	Vapor Pressure (Mbar/20ºc)	:	Not applicable
10.0	**STABILITY AND REACTIVITY**		
10.1	Stability	:	Stable under normal condition
10.2	Condition To Avoid	:	Hot areas
10.3	Materials To Avoid	:	Strong Oxidizing Agents
10.4	Hazardous Decomposing Products	:	Oxides Of Carbon, Nitrogen And Sulphur
10.5	Hazardous Polymerization	:	Not applicable
		:	Not applicable
11.0	**TOXICOLOGICAL INFORMATION**	:	According to experience no harmful effects Are to be expected under proper handling conditions
12.0	**DEGRADABILITY**	:	Not biodegradable
13.0	**DISPOSING CONSIDERATIONS**		
13.1	Waste Disposal Method	:	Recycle when possible. Incinerate in accordance to local regulations
13.2	Contaminated Packaging	:	Observe local regulations.
14.0	**TRANSPORT INFORMATION**	:	Not classified in RID/ADR-ADNR-IMDG/ICAC/IATA-DGR
15.0	**REGULATORY INFORMATION**		
15.1	ECC Classification	:	Not dangerous within the meaning of Directive 67/548/ECC
15.2	Inventory Status	:	Not listed on EINECS (EC). TSCA-CSI (USA), DSL (Canada), AICS (Australia) And MITI (Japan)
15.3	Water Endangering Class	:	0- not water endangering
16.0	**OTHER INFORMATION**		
16.1	Literature Reference	:	Not available